



Cardinal Health
Convertors® Products
1500 Waukegan Road
McGaw Park, IL 60085
847.473.1500

www.cardinal.com

CARE INSTRUCTIONS

Product: Endura™ Performance Apparel Scrub

Wash: Do not overload the washer; fabric should float freely. Process as ordinary colored fabrics; temperature should not exceed 165 degrees Fahrenheit. Do not bleach. Do not use fabric softeners.

Drying Cycle: Do not overload dryer. Fabric should float freely. Tumble dry low; temperature should not exceed 185 degrees Fahrenheit. As with all polyesters, excessive heat will detract from the permanent press characteristics of the fabric. Remove from dryer immediately.

Finish: Do not hand iron. Tunnel finish if desired; temperature not to exceed 185 degrees Fahrenheit.